

Accident: Wing detached from ICP Savannah 912.

Date: 29. June 2005

Place: Lakselv, Northern Norway



Picture 1: Main wing strut connection plate into the wings main beam. This picture shows an ICP Bingo, which seems to have an identical construction. Picture has been flipped over to resemble picture below.



Picture 2: How the connection plate broke near the first bolt at the left-hand wing.



Picture 3: Similar as picture 1, but right-hand wing.



Picture 4: The right-hand wing of the wreck shows a crack at a similar place on the connection plate.



Picture 5: Inspection can be difficult through the narrow slot.



Picture 5: Bright light could improve the quality of the inspection. A suggestion of cutting the plate a few cm to expose the critical location has been proposed.